

DOT. FILE
No. 51
.....
~~~~~

Anchorage, Alaska  
July 23, 1951

To: G. A. Benedict, Supt. of MP&E  
From: Roy V. Boyd, Supt. of Operations  
Subj: AX report No. 149

Please advise what action has been taken regarding investigation on Accident Report No. 149 where Engineer Engle stated feed valve on engine 557 was defective.

SIGNED: ROY V. BOYD

Roy V. Boyd

RVB:gt  
cc - John E. Manley

The Alaska Railroad  
RECEIVED  
JUL 24 1951  
Office of  
Asst. General Manager